

IDENTIFYING AN AFFECTED HELMET

To identify an affected 509 for Polaris Tactical 3.0 helmet, look for the following:

- Helmet is branded "Polaris".
- Helmet includes "Tactical 3.0" printed on it.
 - Blue, Black, and Retro (red/white/blue) helmets - "Tactical 3.0" will be printed on the helmet shell in the cheek area.
 - Teal/Lime helmets - "Tactical 3.0" will be printed on the helmet shell on the upper rear of the head area.
- Certification tag on the chin strap begins with "06301125".



Teal/Lime
2865411 / 2865419 (Youth)



Blue
2865412 / 2865420 (Youth)



Retro
2865409



Black
2865408 / 2865418 (Youth)

<p>① Tactical 3.0</p>	<p>③ Certification Tag on the Chin Strap</p> 
<p>② Polaris</p>	

DESTRUCTION PROCEDURE

To properly destroy the affected helmet, cut the chin straps and get the required photo following these steps:

1. Turn the helmet over to access the chin straps.




2. Remove cheek pads to expose chin straps.



3. Locate the certification tag and verify the number on strap to make sure the helmet is affected by this recall. The first 8 digits on this label read **06301125**.



4. Cut straps in location as indicated.



5. Take a photo capturing both straps cut from the helmet and clearly showing certification tag on strap.

IMPORTANT

The certification tag must be clearly showing in the photo and is readable or you will be asked to retake it to receive a refund, credit, or helmet replacement.



6. Send the photo to Owner.Connections@Polaris.com.

NOTICE

Owners of affected Tactical 3.0 helmets that do not have Polaris logos/branding should send the photo to support@ride509.com.